

***BTP***  
*Belt Tensioner Pulley*



**CATÁLOGO 2026**  
**SOPORTES DE CARDAN**

Código	Descripción	Foto
HB 88107	<b>Soporte Cardan Ø35 Ford - Fiat - Volkswagen - Chevrolet S10</b>	
HB 88508	<b>Soporte Cardan Ø40 Ford Duty - Fiat - Dodge - Volkswagen - Chevrolet - Bedford</b>	
HB 88509	<b>Soporte Cardan Ø45 Chevrolet - Ford - Volkswagen - Volvo - M. Benz - Iveco</b>	
HB 88510 AC	<b>Soporte Cardan Ø50 Ford - M. Benz - Volkswagen - Renault</b>	
HB 88512	<b>Soporte Cardan Ø60 Ford - Fiat - M. Benz - Scania - Volvo</b>	
VKQA 60062	<b>Soporte Cardan Ø30 Toyota Hilux 4X2 hasta modelo 2005</b>	
VKQA 60066	<b>Soporte Cardan Ø30 Isuzu 4X4</b>	

<p><b>VKQA 62068</b></p>	<p><b>Soporte Cardan Ø30 Toyota Hilux 4X2 y 4X4, desde 2005 a 2015</b></p>	
<p><b>VKQA 62069</b></p>	<p><b>Soporte Cardan Ø30 Toyota Hilux 4X2 y 4X4, desde 2016 en adelante</b></p>	
<p><b>VKQA 66009</b></p>	<p><b>Soporte Cardan Ø45 M. Benz Sprinter 308cdi, 311cdi, 313cdi, 411cdi, 413cdi, 414cdi</b></p>	
<p><b>VKQA 66214</b></p>	<p><b>Soporte Cardan Ø30 Nissan Frontier 4X2</b></p>	
<p><b>VKQA 66216</b></p>	<p><b>Soporte Cardan Ø30 Nissan Frontier 4X4</b></p>	
<p><b>VKQA 66269</b></p>	<p><b>Soporte Cardan Ø45 Volkswagen Amarok R2h0521102</b></p>	
<p><b>VKQA 11602</b></p>	<p><b>Soporte de Cardan Ø40 Ford Ranger 2.5 - 2.8 TD Maxion Power Stroke / Ranger 2.3 - 2.5 N</b></p>	

**VKQA 11604**

**Soporte Cardan Ø36 Ford Ranger 3.2 Tdci  
Duratorq**



**VKQA 88118**

**Soporte Cardan Chevrolet S10 2.8 TDI  
Electronic - 2.8 CDTI 180cv - 2.8 CDTI  
200cv**



# **BTP**

***Belt Tensioner Pulley***



**+54 9 11 3151-0372**



**belttensionerpulley**



**Fernández De Oliveira 3353,  
Caseros, Provincia de Bs. As.**



**ventas@tensoresbtp.com**